

Fig. 5. Method of holding
Three Siws of Work which has
be«n bored
and faced and has had
the Holes drilled *In*

finished portion of the base C. All other portions of the* fixture are. the same as in the preceding instance, the clumps // being moved outward in the T-slots a sufficient amount to take care

Flange

of the work of larger diameter, The tools for boring, facing, and cutting the packing grooves P are also the same.